

WINTER INDOOR AIR QUALITY PLAN



Narrabundah Early Childhood School Winter Indoor Air Quality Plan	
Background:	<p>ACT Health has advised that schools optimise fresh air circulation as one of the controls to reduce the risk of COVID-19 transmission in schools.</p> <p>The risk of COVID-19 transmission is higher in crowded and poorly ventilated spaces where people spend long periods of time together in close proximity. Good ventilation is one part of a suite of controls to minimise transmission in schools, like vaccination, physical distancing, student cohorting, good hygiene, cleaning and mask use.</p> <p>This Plan identifies actions that have been undertaken at your school by the Education Directorate and provides additional measures for the school to undertake to optimise the fresh air ventilation in the school.</p>
Health Advice:	<p>The Chief Health Officer, the Australian Health Protection Principal Committee, World Health Organisation, OzSAGE and Safe Work Australia all recommend good indoor air quality to reduce the chance of COVID-19 transmission.</p>
Advice:	<p>The ventilation systems at Narrabundah Early Childhood School have been assessed by the Directorate in accordance with the WHO guidance.</p> <p>Fresh air will be provided through a mix of natural ventilation (opening windows/louvres and doors) and mechanical ventilation via heating ventilation and air-conditioning (HVAC) systems.</p> <p>Increasing the fresh air to classrooms may increase energy costs. Classrooms are also likely to experience lower room temperatures during cooler weather and higher room temperatures during warmer weather.</p> <p>Learning and teaching spaces with fresh air ventilation from either natural or mechanical systems meet the COVID-19 Health Advice. The school is to prioritise the use of these spaces for indoor teaching and learning along with outdoor spaces.</p>

WINTER INDOOR AIR QUALITY PLAN



<p>Daily actions to be undertaken by the school:</p>	<p>Additional daily measures the school will undertake include:</p> <ul style="list-style-type: none"> • Opening windows/louvres and doors in teaching spaces and other shared spaces of the school to supplement fresh air, balancing thermal comfort and ventilation. Windows above ground level are to be opened only where window restriction is in place to ensure student safety. In line with the National Construction Code, window opening is to be 125mm or less. • Improving air circulation through use of ceiling fans and split system air-conditioning units, only when windows are open. • Ensure bathroom, kitchen and any other exhaust fans are on and operating at full capacity while the school or program is operating and for some time before and after occupancy.
<p>Actions undertaken:</p>	<p>The following actions have been undertaken by the Directorate and its service providers to increase fresh air ventilation in the indoor teaching and learning spaces at the school:</p> <ul style="list-style-type: none"> • heating, ventilation and air conditioning (HVAC) systems will continue to operate for two hours after the last expected occupancy to purge spaces with fresh air • HVAC systems have been programmed to supply additional fresh air via the mechanical ventilation systems • CO₂ sensors linked to the HVAC systems at the school will monitor indoor air quality and adjust fresh air while maintaining thermal comfort • portable CO₂ monitors are being provided to the school for naturally ventilated spaces to proactively manage ventilation and thermal comfort through colder weather • guidance documentation has been provided to the school to proactively manage naturally ventilated rooms to balance indoor air quality and thermal comfort through colder weather • 3 withdrawal rooms and the music, arts and craft room are identified as requiring further investigation to ensure they meet the higher ventilation requirements of COVID-19 Health Advice. These classrooms are identified as pink on the attached map. The use of these spaces is to be limited until investigations can take place and the school is advised that they meet the ventilation requirements. These investigations are currently under way. • UV-C light units have been retrofitted to the canteen and 3x cot room air conditioning systems to neutralise airborne virus particles. In these rooms, the systems must be in operation when the room is occupied. • contractors will continue to maintain HVAC systems • contractors will continue window maintenance and replacement to support natural ventilation where required

WINTER INDOOR AIR QUALITY PLAN



Support or further advice:	For further advice, schools can contact their ICW Network Officer or email ACT.Education@act.gov.au
-----------------------------------	---